

THE ORISSA MINERALS DEVELOPMENT CO. LTD.

(A GOVT. OF INDIA ENTERPRISE)

MANGANESE & IRON ORE MINES

Telegraphic Address:

“Shoveller”, Barbil
Telephone: Office: 275218,275382
275530

Fax: 91-6767-275382

Regd. Office:

AG-104, Sector-II, Salt Lake City,
KOLKATA – 700 091
Email: info.birdgroup@nic.in
Tel. No.2321-3983,
Fax. No. 033- 2321-3874

Mines Office:

P.O. Thakurani
Via-Barbil-758 035
Dist. Keonjhar (Orissa)
Email : omdcpurchase@rediffmail.com
Website: www.birdgroup.gov.in

In your reply please quote Ref. No. **OMD/S-1**

Dated-13/01/2011

Sub : Fabricating & Repairing of TATA-1210, Water Lorry being laying under breakdown condition at Central Work Shop at Thakurani.

Dear Sirs,

Enclosed please find herewith a list of jobs which need to be carried out for fabricating & repairing of Tata-1210, Water Lorry with various spare parts and would request you to kindly send/submit your sealed estimate/quotation offer as per Annexure-I mentioning all terms and conditions along with delivery period & guarantee of the job which must reach the undersigned on or before **24/01/2011** positively.

It is to be mentioned here that if the agency will carry out the repairing in his own garage, then the lorry is to be shifted by toeing with Break Down Vehicles with his own arrangement at free of cost. Company will not pay in this regard.

The job will be awarded to lowest bidder on aggregating total value of all the items & will not be divided.

Encl: As above

N.B: Please super scribe our Enquiry number & date on the top of the Envelope.

Yours faithfully
THE O.M.D. CO. LTD
Sd/-
ASST. MANAGER (O)

ANNEXURE-I

| Sl. No | Description of Job | Quantity |
|---------------|--|-----------------|
| 1 | Cabin Top Changing | 01 No |
| 2 | Front Bumper Changing | 01 No |
| 3 | Chassis Straightening, Repairing with 50mm x 12mm M.S. Flat and Aligning | 01 No |
| 4 | Door Repairing both side with glass channel, door lock door handle, door machine for shuttering making | 01 Lot |
| 5 | Diesel Tank repairing | 01 No |
| 6 | Front Glass frame repairing, glass fitting with rubber Beading with key | 01 Set |
| 7 | Complete desk board repairing & doubling | 01 No |
| 8 | Desk board mounting and complete U-Bolt replacement | 10 Nos |
| 9 | U-Bolt of front leaf spring change with new supply | 02 Sets |
| 10 | Water tank damaged portion M.S.Sheet cutting & new Welding | 01 No |
| 11 | Cabin Leaf spring set change | 01 Set |
| 12 | 4 Wheel leaf spring set hight developing and broken pieces Changing | 04 Sets |
| 13 | Dumper Bucket (Dala) repairing with supplying of M.S.Sheet, Angle & Channel | 01 Lot |
| 14 | Pilot and Helper seat both new making and erecting with supplying rexine, foam & wooden frame etc | 02 Nos |
| 15 | Engine bonnet new replacement | 01 No |
| 16 | Cabin Ceiling making, washing and repairing | 01 No |
| 17 | Radiator cleaning, Washing & repairing | 01 No |
| 18 | Front & Rear indicator for parking brakes and L/R indicator Assy. New supplying and erecting | 02 Sets |
| 19 | Front Head light assy. for L/R new supplying and erecting | 01 Set |
| 20 | Cabin light new supplying and fitting | 01 Set |
| 21 | M.Rod new supplying and erecting | 02 Nos |
| 22 | Looking Mirror holder fabricating and new supplying for L/R | 02 Sets |
| 23 | Fuse Box set change new supply | 01 Set |
| 24 | Cabin Shock absorber new suppling and change | 02 Nos |
| 25 | Engine Mounting Bolt new supplying and fitting | 04 Nos |
| 26 | Denting and painting of complete water lorry | 01 Lot |
| 27 | Others Jobs arises during progressing of the work | |